

## HAZARDOUS WASTE INVESTIGATION

HW/EP 02-01

Inspector: Al Iannuzzi, Jr. *AI Jr.* Date: 10/27/82

Location: Scientific Chemical Processing, Inc.

Site: 216 Paterson Plank Rd. Property Owner: Inmar Associates, Inc.

Town: Carlstadt

P. O. Box 190  
1703 E. Second St.  
Scotch Plains, NJ 07076

County: Bergen

Lot: 1 and 5

Block: 124

Origin of Complaint: Weekly monitoring

Complaint: Follow-up of 10/21/82 investigation

## Findings:

1220 hours Arrived on site.

Pat Parretti of Pat Parretti Freight (trucking co. operating on site) was contacted.

Conditions remain the same since the previous inspection. Attached diagram indicates leaks, spills, and vehicles on site.

A total of 14 rusted metal 55 gallon drums were noted on the rear elevated cement pad. Most of the drums were not covered and some contained solid material and rainwater. These drums have been on site for a long period of time and have been noted in this report to stress their poor condition and storage.

Trailer #14 is still leaking. The resulting spill of brown sludge is getting larger (is now approx. 6' x 1') and has gotten into a puddle of standing water.

1430 hours Left site.

Photos/samples

No photos or samples were taken.

cc: DAG Dave Reiger


SDMS Document



67628

000206

0  
1  
Г  
Э  
2  
5  
2  
4  
Р  
!  
1  
4  
K  
R  
3  
K  
D



pile of empty  
drums and garbage